



*Referenced to Nigeria Regulations*

# Advisory Circular

**NCAA-AC-ARD018**

**NIGERIA CIVIL AVIATION AUTHORITY (NCAA)**  
**ISSUE NO 1**

**DATE: 17<sup>TH</sup> JULY, 2023**

## PROCEDURE FOR MOVEMENT AREA CLOSURE

Made this <sup>17<sup>th</sup></sup> ..... day of <sup>July</sup> ..... 2023

**Captain Musa Shuaibu Nuhu**

Director General of Civil Aviation



## 1.0 GENERAL

The Nigeria Civil Aviation Authority's Advisory Circulars contains information about standards, practices and procedures that the Authority has found to be an Acceptable Means of Compliance (AMC) with the associated Regulations.

An AMC is not intended to be the only means of compliance with a Regulation, and consideration will be given to other methods of compliance that may be presented to the Authority

Information considered directive in nature is described in this AC in terms such as "shall" and "must", indicating the actions are mandatory. Guidance information is described in terms such as "should" and "may" indicating the actions are desirable or permissive, but not mandatory.

## 2.0 PURPOSE

This Advisory Circular provides methods acceptable to the authority, for showing compliance with the requirements of the Nig.CARs Part 12 for movement area closure as well as explanatory and interpretative material to assist in showing compliance.

## 3.0 APPLICABILITY

This AC applies to operators on Aerodrome Certification, Safety Assessments and Aerodrome Compatibility

## 4.0 REFERENCE

- (a) Nig.CARs Part 12.1.1.5 – Design/Operation of Aerodromes
- (b) Nig.CARs Part 12.1.2 – Aerodrome Certification and Administration

## 5.0 STATUS OF THIS AC

This is the first AC to be issued on this subject



## AMENDMENT PROCEDURES

The Director, Aerodrome and Airspace Standards is responsible for the development, issuance and control of amendments to this document as well as ensuring that the AC is updated in the technical library for staff and the website [ncaa.gov.ng](http://ncaa.gov.ng) for public use.

Each page will show the document number, issue/amendment number, issue date and page number at the base of the page.

All amendments must be recorded in the Record of Amendments.

Any observation made or contribution to the content of this document by the user should be directed to the following address for consideration and adoption

**Nigeria Civil Aviation Authority**

**Corporate Headquarters**


**Nnamdi Azikiwe International Airport,**

**FCT, Abuja.**



## RECORD OF AMENDMENTS

Issue No/ Amendment No	Page(s) Affected	Date Entered	Entered By	Signature
1/0	All	12 <sup>th</sup> June, 2023		





## LIST OF EFFECTIVE PAGES

Chapter	Page	Date of issue
APPROVAL PAGE	Cover	12 <sup>th</sup> June, 2023
AMENDMENT PROCEDURE	3	12 <sup>th</sup> June, 2023
RECORD OF AMENDMENT	4	12 <sup>th</sup> June, 2023
LIST OF EFFECTIVE PAGES	5	12 <sup>th</sup> June, 2023
TABLE OF CONTENT	6	12 <sup>th</sup> June, 2023
CHAPTER 1	7	12 <sup>th</sup> June, 2023
CHAPTER 2	8-9	12 <sup>th</sup> June, 2023
CHAPTER 3	10	12 <sup>th</sup> June, 2023
CHAPTER 4	11	12 <sup>th</sup> June, 2023



# Table of Contents

<b>1.0 GENERAL</b> .....	<b>2</b>
<b>2.0 PURPOSE</b> .....	<b>2</b>
<b>3.0 APPLICABILITY</b> .....	<b>2</b>
<b>4.0 REFERENCE</b> .....	<b>2</b>
<b>5.0 STATUS OF THIS AC</b> .....	<b>2</b>
<b>AMENDMENT PROCEDURES</b> .....	<b>3</b>
<b>RECORD OF AMENDMENTS</b> .....	<b>4</b>
<b>LIST OF EFFECTIVE PAGES</b> .....	<b>5</b>
<b>CHAPTER 1</b> .....	<b>7</b>
<b>BACKGROUND</b> .....	<b>7</b>
<b>CHAPTER 2</b> .....	<b>8</b>
<b>2.0 GENERAL REQUIREMENT</b> .....	<b>8</b>
<b>2.1 Notification of Changes</b> .....	<b>8</b>
<b>2.2 Marking of Closed Runway and Taxiway or Parts Thereof</b> .....	<b>8</b>
2.2.1 Application.....	8
2.2.2 Location.....	8
2.2.3 Characteristics.....	8
<b>CHAPTER 3</b> .....	<b>10</b>
<b>USE OF LIGHTED VISUAL AID</b> .....	<b>10</b>
<b>CHAPTER 4</b> .....	<b>11</b>
<b>SUMMARY OF ACTIONS REQUIRED FOR MOVEMENT AREA CLOSURE</b> .	<b>11</b>
4.1 Permanently Closed Runways/Taxiways.....	11
4.2 Temporarily Closed Aerodrome.....	11
4.3 Permanently Closed Aerodrome.....	11



## CHAPTER 1

### BACKGROUND

Globally, there have been instances of aircraft landing on runways that are temporarily closed for maintenance resulting in serious accident and significant loss to airline owner in terms of damage to aircraft and payment of huge sums as compensation attributed to inadequate oversight. The likelihood of unintended landings increases during periods of reduced visibility and at night whenever runway lighting must be on for electrical maintenance. The lighted visual aid is intended to eliminate ambiguity concerning the status of the runway and to reduce instances of aircraft landing on temporarily closed runways.





## CHAPTER 2

### 2.0 GENERAL REQUIREMENT

#### 2.1 Notification of Changes

The Nig.CARs Part 12.1.4.10B

**“Notification of changes to the Aerodrome facilities, equipment and level of service planned in advance** - An Aerodrome operator shall notify the Authority, in writing at least 60 days, before effecting any change to the Aerodrome facility or equipment or the level of service at the Aerodrome that has been planned in advance.”

#### 2.2 Marking of Closed Runway and Taxiway or Parts Thereof

The Nig.CARs Part 12.2.7 stipulates the relevant requirements.

##### 2.2.1 Application

###### 2.2.1.1 Permanently Closed Runway or Taxiway

A closed marking shall be displayed on a runway or taxiway, or portion thereof, which is permanently closed to the use of all aircraft.

###### 2.2.1.2 Temporarily Closed Runway or Taxiway

A closed marking should be displayed on a temporarily closed runway or taxiway or portion thereof, except that such marking may be omitted when the closing is of short duration (less than 3 days) and adequate warning by air traffic services is provided.

##### 2.2.2 Location

On a runway, a closed marking shall be placed at each end of the runway or portion thereof, declared closed, and additional markings shall be so placed that the maximum interval between markings does not exceed 300m. On a taxiway, a closed marking shall be placed at least at each end of the taxiway or portion thereof closed.

##### 2.2.3 Characteristics

(a) The closed marking shall be of the form and proportions as detailed in the Nig.CARs Part 12.2.7 Figure 7-1, Illustration (a), when displayed on a runway, and shall be of the form and proportions as detailed in Nig.CARs Part 12. Figure 7-1.Illustration (b),

when displayed on a taxiway. The marking shall be white when displayed on a runway and shall be yellow when displayed on a taxiway.





*Note – When an area is temporarily closed, frangible barriers or markings utilizing materials other than paint or other suitable means may be used to identify the closed area.*

- (b) When a runway or taxiway or portion thereof is permanently closed, all normal runway and taxiway markings shall be obliterated.
- (c) Lighting on a closed runway or taxiway or portion thereof shall not be operated, except as required for maintenance purposes.
- (d) In addition to closed markings, when the runway or taxiway or portion thereof closed is intercepted by a usable runway or taxiway which is used at night, unserviceability lights shall be placed across the entrance to the closed area at intervals not exceeding 3m.



## CHAPTER 3

### USE OF LIGHTED VISUAL AID

A very effective and preferable visual aid to depict temporary closure is the use of lighted "X" signal. If the lighted "X" is not available, construct the marking of any of the following materials: double-layered painted, colored plastic, painted sheets of plywood, or similar materials. They must be properly configured and secured to prevent movement by prop wash, jet blast, or other wind currents.





## CHAPTER 4

### SUMMARY OF ACTIONS REQUIRED FOR MOVEMENT AREA CLOSURE

#### 4.1 Permanently Closed Runways/Taxiways

For runways and taxiways that have been permanently closed, disconnect the lighting circuits. For runways, obliterate all runway markings, and place "X's" at each end and at (300-m) intervals. For taxiways, place an "X" at least at the entrance of the closed taxiway. Provide appropriate notification by NOTAM, voice advisory and subsequently AIP and with prior notice given to the Authority.

#### 4.2 Temporarily Closed Aerodrome

When the airport is closed temporarily, mark the runways as closed as given in paragraph 2.2.1.2 above and turn off the airport beacon. Provide notification by voice advisory and NOTAM and inform the Authority in advance.

#### 4.3 Permanently Closed Aerodrome

When the airport is closed permanently, mark the runways as permanently closed as given in paragraph 2.2.1.1 above, disconnect the airport beacon, and place an "X" in the segmented circle or at a central location if no segmented circle exists. Notify the Authority in advance of the closure of the aerodrome and provide the required information for promulgation in the AIP.